**MOONEY AIRPLANE COMPANY** 

## SERVICE INSTRUCTION



Louis Schreiner Field Kerrville, Texas 78028

## THIS SERVICE INSTRUCTION DOES NOT CHANGE AIRCRAFT TYPE DESIGN

SERVICE INSTRUCTION M20-109 Date: 15 February, 2003

SUBJECT:	Fastener Installation	Torque of Nose Gea	r Steering Pivot Bolt.

MODELS/ S/N	-M20C – All
AFFECTED:	

- -M20D All
  - -M20E All
- -M20F All
- -M20G All
- -M20J All
- -M20K All
- -M20L All
- -M20M All
- -M20R All
- -M20S All
- TIME OF NEXT 100 HOUR INSPECTION COMPLIANCE:
- INTRODUCTION: Mooney Aircraft Corporation *Service and Maintenance Manual* specify torque of the nose gear steering pivot bolt, AN7-50 or NAS1307-72D with AN310-7 nut, to be retorqued to 450-500 inch-pounds every 100 hour inspection. (Reference *Service and Maintenance Manual* section 32-50-01.) Mooney Aircraft has determined that retorque to 450-500 inch pounds in some cases can cause excessive resistance to rotation of the nose gear.
- INSTRUCTIONS: During the 100 hour inspection, after inspection of the bolt and bolt holes, torque the bolt and nut to 270-300 inch-pounds.

Some resistance to rotation of the nose gear pivot may be noticed, this is normal.

WARRANTY: None. Aircraft maintenance.