MOONEY AIRCRAFT, INC.

LOUIS SCHREINER FIELD . KERRVILLE, TEXAS

Service Bulletin

1\ (h - 1

NUMBER 6

DATE: 5-1-64

(This Service Bulletin F. FAA Approved)

This Service Bulletin reidentified as Service Instruction M.2a - 2/per Service Instruction M20-15.

SUBJECT:

Fuel Pressure Gauge

MODELS AFFECTED:

M20E

101 thru 218

TIME OF COMPLIANCE:

When necessary to correct fuel pressure fluctuations

INTRODUCTION:

There are some M20E that have reported fluctuations of the flux pressure indications on the fuel pressure gauges. We, therefore, suggest that a Garwin restrictor P/N 22-627-01 he used This restrictor has a Smaller orifice which will aid in dampening out of the fluct pressure needle. Some of the aircraft listed above may have had this restrictor premously installed. Quick identification of the restrictors are provided for by a color code. The original Morney restrictor was blue and the Garwin restrictor is red.

INSTRUCTIONS:

- Disconnect fuel line from back of fuel pressure gauge.
- 2. Remove original restrictor.
- 3. Install Garwin Restrictor 22-627-01,
- 4. Connect fuel line back to gauge.
- Pressure check for leaks.

SERVICE BULLETIN NO. 6 PARTS LIST:

Parts Required: Garwin Restrictor No. 22-627-01

NOTE: This will be supplied at no charge upon request from your local Mooney Distribut-