MOONEY INTERNATIONAL CORPORATION

SERVICE INSTRUCTION



165 Al Mooney Road North Kerrville, Texas 78028

SERVICE INSTRUCTION SIM20-145

Date: January 03, 2023

SUBJECT: 430018-1 Hybrid Elevator Weights on Mooney Aircraft with Smooth Skin Elevators

per Mooney Service Bulletin M20-345A.

MODELS/ SN AFFECTED: M20C, M20D, M20E, M20F, M20G serial numbers 680170 or earlier.

TIME OF COMPLIANCE:

USE IN ACCORDANCE WITH SERVICE BULLETIN M20-345A

INTRODUCTION:

There are specific M20F aircraft with smooth skin elevators 430000-503 (LH), 430000-504 (RH) identified with 9 rib lines, that utilized a hybrid material elevator balance weight. These weights (P/N 430018-1) are identified by the center plug made of chromoly tubing and lead running through the full width of the balance weight. During routine maintenance at an Authorized Mooney Service Center, the elevator balance weights were found to have developed galvanic corrosion, visible signs of the weight is cracked and displaced severely. There have been several instances of this anomaly reported only on M20F aircraft using this hybrid balance weight. Based on original service center discoveries and field reports from the initial released version of this service bulletin, Mooney engineering requests that all 430018-1 hybrid weights be removed and replaced with the 430016-7 lead weights.

If the balance weight is determined to be a hybrid weight 430018-1, and initial inspection per Mooney Service Bulletin M20-345A shows no sign of cracking or chipping, the attached Temporary Change Notice will be required for continued flight, until the 430018-1 balance weight has been replaced per Mooney Service Bulletin M20-345A, refer to **FIGURE SIM20-145-1 and FIGURE SIM20-145-2**.

WARRANTY: N/A

REFERENCE DATA:

Mooney Service Bulletin M20-345A (or later FAA Approved Revision)
 Mooney POH-001194 Issued September 1966, Revised March 1967

PARTS LIST: Service Instruction Kit - N/A

MOONEY INTERNATIONAL CORPORATION

SERVICE INSTRUCTION



165 Al Mooney Road North Kerrville, Texas 78028

SERVICE INSTRUCTION SIM20-145

Date: January 03, 2023

THIS PAGE INTENTIONALLY LEFT BLANK

MOONEY INTERNATIONAL CORPORATION

SERVICE INSTRUCTION



165 Al Mooney Road North Kerrville, Texas 78028

SERVICE INSTRUCTION SIM20-145

Date: January 03, 2023

AIRPLANE OWNER'S MANUAL TEMPORARY CHANGE NOTICE JANUARY)#, 2023 **REVISION IR** TCN22-001 Elevator Weights 430018-1 Title: Effectivity: M20F: Per SB M20-345A (all serial numbers 680170 or earlier) M20F (POH-001194) Issued: September 1966 Revised March 1967 Instructions: insert between pages 20 and 21. There are specific M20F aircraft with smooth skin elevators 430000-503 Reason for Change: (LH), 430000-504 (RH) identified with 9 rib lines, that utilized a hybrid material elevator balance weight. These weights (P/N 430018-1) are identified by the center plug running through the full width of the balance weight. During routine maintenance at an Authorized Mooney Service Center, the elevator balance weights were found to have developed galvanic corrosion, visible signs of the weight is cracked and displaced Changes to PART I: DESCRIPTION AND OPERATION OF COMPONENTS ... No Effect PRE-FLIGHT INSPECTION 3A. Check Elevator weights for signs of cracking or chipping (see Reason **FRIM LINE** for Change above). If cracking or chipping is found, DO NOT FLY until further inspection has been performed. Reference Mooney service bulletin M20-345A or later FAA Approved revision for details. Authorization to Remove this TCN from the Owner's Manual: This TCN is in effect until 430018-1 Elevator Weights have been replaced. Reference Service Bulletin M20-345A or later FAA Approved revision. AIRPLANE OWNER'S MANUAL TCN 23-001 **ADDENDUM** Rev: IR

Figure SIM20-145-1 - TEMPORARY CHANGE NOTICE

MOONEY INTERNATIONAL CORPORATION - 165 AI Mooney Road North, Kerrville, Texas 78028 tel: 830-896-6000 www.mooney.com



165 Al Mooney Road North Kerrville, Texas 78028

SERVICE INSTRUCTION SIM20-145

Date: January 03, 2023 AIRPLANE OWNER'S MANUAL TEMPORARY CHANGE NOTICE JANUARY 03, 2023 REVISION IR THIS PAGE INTENTIONALLY TRIM LINE LEFT BLANK TCN23-001 Rev: IR AIRPLANE OWNER'S MANUAL **ADDENDUM**

Figure SIM20-145-2 - TEMPORARY CHANGE NOTICE

SERVICE INSTRUCTION



165 Al Mooney Road North Kerrville, Texas 78028

SERVICE INSTRUCTION SIM20-145
Date: January 03, 2023

MOONEY INTERNATIONAL CORPORATION

SERVICE (BULLETIN) (INSTRUCTION) NO	SIM20-145	HAS BEEN COMPLIED
WITH ON AIRCRAFT MODEL	SERIAL NUMBER	
Fach. Time:	N-Number .	(Reg. No.
Owner:	Date of Compliance:	
	-	
nspection Report:		
Form 07-0001		
		PLACE STAMP HERE
MOONEY INTI ATT'N: TECHNIC 165 AI Mooney R Kerrville, Texas 7	AL PUBLICAT	L CORPORATION TIONS DEPT

SEND ALL COMPLIANCE CARDS TO:

Mooney International Corporation ATTN:Product Support Dept. 165 Al Mooney Road North Kerrville, TX 78028

FAX: (830) 257-4635 or EMAIL TO: support@mooney.com

To submit Technical Publication changes, visit our website: https://www.mooney.com/service or email a request to: techpubs@mooney.com