This Service Letter reidentified as Service Bulletin M 20-13 per Service Instruction M20-15.

EY AIRCRAFT, INC. KERRVILLE, TEXAS

## SERVICE LETTER 20-13

DATE:

6-7-56

SUBJECT:

. Kit Turn & Bank Indicator Mounting Spacer.

MODELS AFFECTED: 1002 Thru 1043

PARTS LIST:

8145 (1)

AN515-6R-16(1) AN515-6R-24(1) AN960-6L (2)

In several cases the turn and bank indicator on the M-20 has been replaced becaused it was not working properly. This is probably due to the fact that it is not mounted parallel to the line of thrust. In an attempt to correct this situation, a spacer is now being installed on production models. This kit is enclosed without charge for installation on units in the field as shown in figure one.

