

SUBJECT: Replacement of Garwin Turn and Bank Indicator, Part No. 23-477-07A, and/or Mooney Part No. 820124

MODELS AFFECTED: M20C, S/N 2742, 2807 thru 3459
M20E, S/N 400, 470 thru 1212

TIME OF COMPLIANCE: Within the next 100 hours

INTRODUCTION: Garwin, Inc. has incorporated design features in the turn and bank indicator, part no. 23-477-07A, which will extend its service life. All indicators of the shown part number not having "CL-1" stamped on the instrument case are affected. Any instrument having the "CL-1" stamp is not affected by this Bulletin. Log Book entries should be made to show compliance with this Service Bulletin.

INSTRUCTIONS:

1. Remove Royalite instrument panel cover.
2. Remove electrical connector from back of instrument.
3. Remove instrument mounting screws.
4. Install the new instrument in the same manner as the old instrument was installed.

PARTS LIST: Garwin Turn and Bank Indicator, Part No. 23-477-07A, with CL-1 marking.

COMPLIANCE: This instrument is available upon request from your local Mooney distributor.

All Turn and Bank, P/N 23-477-07A, from the aircraft serial numbers as listed in this Bulletin, warranty credit will be extended upon receipt of this old unit on/or before November 15, 1967.