THIS SERVICE BULLETIN IS FAA APPROVED FOR ENGRG.DESIGN

MOONEY AIRCRAFT CORPORATION LOUIS SCHREINER FIELD KERRVILLE, TX. 78028

SERVICE BULLETIN M20-236 DATE: 6-27-88

SUBJECT: PORSCHE PFM 3200 SERVICE BULLETIN NO. N/301-020, ENGINE SUSPENSION SYSTEM INSPECTION.

MODEL /S/N

AFFECTED: MOONEY MODEL M20L, S/N 26-0001 THRU 26-0016, 26-0018,26-0020,26-0021

26-0023 THRU 26-0025

TIME OF

COMPLIANCE: AT EACH OF THE NEXT THREE (3) CONSECUTIVE 100 HOUR OR ANNUAL

INSPECTIONS.

INTRODUCTION:

VARIATIONS IN THE MACHINING PROCESS AND INSTALLATION OF THE "ROSAN-INSERTS" IN FORWARD, UPPER MOUNTING PAD LOCATED ON ENGINE PROPELLER GEARBOX, THE POSSIBILITY EXISTS THAT THE BOLTS SECURING THE ENGINE MOUNTING BRACKET MAY LOSE THE REQUIRED TORQUE VALUE.

INSTRUCTIONS:

REFER TO PORSCHE'S SERVICE BULLETIN NO. N/301-020, DATED: JUNE 2, 1988 (OR SUBSEQUENT REVISIONS) FOR DETAILED INSPECTION REQUIRED.

* NOTICE *

CONTACT PORSCHE AVIATION PRODUCTS, INC., MUNICIPAL AIRPORT, R.R. # 2, BOX 118A, GALESBURG, IL., 61401, TELEPHONE (309) 342-0800, FOR WARRANTY INFORMATION, REPAIR PARTS OR SERVICE INFORMATION.

** NOTICE **

AFTER 1995--CONTACT

PORSCHE AVIATION PRODUCTS, INC. 1600 HOLCOMB AVENUE RENO, NEVADA 89502 (USA) TELE: (702) 329-3937 FAX: (702) 329-0426

REFERENCE

DATA: PORSCHE S.B. NO. N/301-020, DATED JUNE 2, 1988 (OR SUBSEQUENT REVISIONS).

PARTS LIST: REFERENCE PORSCHE S.B. NO. N/301-020, DATED JUNE 2, 1988.

FIGURES/

TABLES: REFERENCE PORSCHE S.B. NO. N/301-020, DATED JUNE 2, 1988.