

THIS SERVICE BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN

MOONEY AIRCRAFT CORPORATION
LOUIS SCHREINER FIELD
KERRVILLE, TX 78028

SERVICE BULLETIN M20-237A
DATED: 1 - 12 - 89

SUBJECT: PORSCHE FM 3200 SERVICE BULLETIN number N/602-023, REVISION 1, ELECTRONIC IGNITION SYSTEM DISTRIBUTORS

MODEL/SN
AFFECTED: MOONEY M20L (MOONEY PFM): S/N 26-0001, 26-0005, 26-0006, 26-0008, 26-0009, 26-0011 THRU 26-2014, 26-0018, 26-0019, 26-0021 THRU 26-0024, 26-0026, 26-0027, 26-0029 THRU 26-0033, 26-0036, 26-0037, 26-0038 THRU 26-0041

TIME OF
COMPLIANCE: AT NEXT 100 HOUR OR ANNUAL INSPECTION

INTRODUCTION: ON SOME AIRCRAFT, IGNITION SYSTEM CHECKS REVEALED A FAILURE OF THE PIN IN THE DRIVE COUPLING OF THE IGNITION DISTRIBUTOR. THE SPIRAL SPRING THAT IS PRESENTLY BEING USED WILL BE REPLACED BY A "PRESSED ON" METAL RING.

INSTRUCTIONS: REFER TO PORSCHE SERVICE BULLETIN NO. /N/602 -023, REVISION 1, DATED DECEMBER 20, 1988 (OR SUBSEQUENT REVISIONS) FOR RETROFIT ACTION REQUIRED.

*** NOTICE *
CONTACT**

**PORSCHE AVIATION PRODUCTS, INC.
1600 HOLCOMB AVE.,
RENO, NEVADA (USA) 89502
TELE. (702) 329-3937
FAX: (702) 329-0426**

REFERENCE
DATA: PORSCHE SB NO. N/602-023, REVISION 1, DATED DECEMBER 20, 1988 (OR SUBSEQUENT REVISIONS).

PARTS LIST: PORSCHE SB NO. N/602-023, REVISION 1, DATED DECEMBER 20, 1988 (OR SUBSEQUENT REVISIONS).

FIGURES/
TABLES: PORSCHE SB NO. N/602-023, REVISION 1, DATED DECEMBER 20, 1988 (OR SUBSEQUENT REVISIONS).