

THIS SERVICE BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN

SUBJECT: MOONEY PFM IGNITION LEAD, REMOVAL AND REPLACEMENT; NOTICE OF  
PORSCHE SERVICE BULLETIN N/602-028, DATED 4-20-89.

MODEL/S/N

AFFECTED: MOONEY M20L, (MOONEY PFM) S/N 26-0001 thru 26-0041 \*

**\* NOTE**

**M20L S/N 26-0004, 0005, 0006, -0008, -0010, -0020, -0021, -0024, -0025, -0032, -0039, -0041  
have had this SB maintenance action accomplished.**

TIME OF

COMPLIANCE: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN N/602-028, DATED 4-20-89.

INTRODUCTION: This Mooney Service Bulletin is to advise Mooney Service Centers of an existing  
Porsche PFM Service Bulletin. REFER TO PORSCHE PFM 3200 SERVICE  
BULLETIN N/602-028, DATED 4-20-89 for modification action to be accomplished.

INSTRUCTIONS: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN N/602-028, DATED 4-20-89.

Porsche has distributed their Service Bulletin to Service Centers known to have Mooney  
PFM aircraft in their area. If copies of the Porsche Service Bulletin are needed order PFM  
SB N/602-028 from the Porsche Aviation Products, Inc. address below.

WARRANTY: N/A - R & R time is minimal.

REFERENCE

DATA: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN N/602-028, DATED 4-20-89.

PARTS LIST: Order parts from:

OLD ADDRESS Porsche Aviation Products, Inc.  
Municipal Airport  
Rural Route 2, Box 118A  
Galesburg, IL 61401  
(309) 342-0800 (Gary Butcher)

NEW ADDRESS Porsche Aviation Products, Inc.  
1600 Holcomb Avenue  
Attn.: Gary Butcher  
Reno, NV 89502  
Tele.: (702) 329-3937  
Fax: (702) 329-0426

FIGURES/

TABLES: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN N/602-028, DATED 4-20-89.