This Service Letter reidentified as Service Balletin M 20-27 per Service Instruction M20-15.

MOONEY AIRCRAFT, INC.

SERVICE LETTER 20-27

DATE:

10-28-57

SUBJECT:

Inspection of seal at nose wheel valve

stem openings.

MODELS AFFECTED:

M20 Serial No. 1002 - 1051

TIME OF COMPLIANCE: Immediate Action Recommended.

There have been a few instances in which dirt and water have entered the nose wheel and caused damage to the wheel bearing.

Each half of the nose wheel has a hole for the valve stem which opens into the hollow area around the bearing. One of these holes should have a rubber sleeve around it to seal these openings. The nose wheels on early airplanes were not so equipped.

The seals are now available and will be sent free of charge on request. Please state airplane serial number on order.