



S.I. No. M20-40

Date: 12-2-76

### SERVICE INSTRUCTION

**SUBJECT:** BAGGAGE COMPARTMENT TIE DOWN STRAP ASSEMBLY REPLACEMENT

**MODELS  
AFFECTED:**

<u>Model</u>	<u>Serial Effectivity</u>
M20F	680001 thru 22-1362, 22-1364, 22-1365, 22-1367, 22-1368, 22-1369, 22-1371 thru 22-1376, 22-1378 thru 22-1381, 22-1385, 22-1386, 22-1388 thru 22-1394, 22-1396, 22-1399 thru 22-1407
M20E	680001 thru 21-1180
M20C	680001 thru 20-1196, 20-1198, 20-1199, 20-1202, 20-1204 and 20-1205
M20G	680001 thru 700006
M22	680001 thru 700006

**TIME OF COMPLIANCE:** At next scheduled inspection or sooner at owner's discretion.

**INTRODUCTION:** On the aircraft noted above the material used for the baggage compartment tie down rings was found to be of an incorrect type. Therefore, it is recommended that the entire tie down strap assemblies be replaced.

**INSTRUCTIONS:** Remove existing baggage compartment tie down strap assemblies and replace with the new assemblies called for by the parts list.

<u>SERVICE INSTRUCTION</u>	<u>Qty.</u>	<u>Part No.</u>	<u>Part Name</u>
KIT S. I. M20-40-1 :			
	2	010003-505	Baggage Strap Assy
	2	010003-507	Baggage Strap Assy
	1	S. I. M20-40 Compliance Card	

**COMPLIANCE:** Make Log Book entry, fill out and return Compliance Card.