

THIS BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN

SERVICE BULLETIN M20-241  
DATE: 2-10-89

SUBJECT: MOONEY PFM, (M20L) CHECK VALVE ON ELECTRIC FUEL PUMPS. REFERENCE  
PORSCHE PFM 3200 SERVICE BULLETIN NO. N/100-025, DATED 11-10-88.

MODEL/

S/N AFFECTED: MOONEY M20L A/C, S/N 26-0001 THRU 26-0041

TIME OF

COMPLIANCE: AT NEXT 100 HOUR INSPECTION

INTRODUCTION: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025.

INSTRUCTIONS: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025.

Depending upon your geographical location, obtain copies of Porsche Service Bulletin's, parts or service support for the PFM 3200 engine from either of the following addresses:

EUROPE, AUSTRALIA, ASIA & AFRICA

Dr. Ing.h.c.f Porsche  
Aktiengesellschaft  
Abt. VF  
Porschestraße 15-19  
Postfach 1108  
D-7140 Ludwigsburg  
Federal Republic of Germany  
Telefon: (49) 07141/39-8396 or 8398  
Telefax: (49) 07141/39-8330  
Telex: 7 264 761

NORTH & SOUTH AMERICA

WAS< Porsche Aviation Products, Inc.  
Municipal Airport  
Rural Route 2, Box 118A  
Galesburg, IL 61401  
(309) 342-0800  
(800) 541-7736  
(800) 747-6772 (IL only)  
Telefax (309) 342-1078

NOW<

Porsche Aviation Products, Inc  
1600 Holcomb Avenue  
Reno, NV 89502  
Tele. (702) 329-3937  
Fax: (702) 329-0426

CAUTION

RESEAL SHROUDS HOUSING THE FUEL PUMPS USING PR1403-G-B2 SEALANT WHEN PORSCHE SB #N/100-025 IS COMPLETED.

WARRANTY: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025.

REFERENCE

DATA: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025.

PARTS LIST: KIT P/N: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025 (MATERIAL).

FIGURES/

TABLES: REFERENCE PORSCHE SERVICE BULLETIN NUMBER, N/100-025 (INSTRUCTIONS) (TOOLS REQUIRED).