

MOONEY AIRCRAFT, INC.

KERRVILLE, TEXAS

SERVICE LETTER 20-73

SERVICE BULLETIN M20-73

DATE: January 24, 1961
SUBJECT: MOONEY FIELD KIT for installation of "Lycoming
Thermostatic Oil Cooler By-Pass Valve"
Re: Lycoming Service Instruction Number 1008
MODELS AFFECTED: M-20A aircraft, Serial No. 1201 thru 1700
TIME OF COMPLIANCE: At owners discretion

INTRODUCTION

The purpose of this service letter is to supplement Lycoming Service Instruction Number 1008.

Oil temperature control is of particular importance during winter-time operation or during extended power-off let down where considerable cooling will occur.

The Lycoming Thermostatic Oil Cooler By-Pass Valve requires the additional parts listed below for its adaptation to all Mooney Mark 20-A aircraft.

PARTS LIST for Service Letter Kit 20-73

1	69451	Thermostatic Oil Cooler By-Pass Valve (Lycoming)
1	69510	Valve & Screen Housing (Lycoming)
1	61173	Valve & Screen Housing Gasket (Lycoming)
1	6438	Adapter (Mooney Aircraft, Inc.)
2	STD 294	Annular Gasket (Lycoming)
1	1649-8D	90° StratoFlex Hose Fitting (StratoFlex, Inc.)
1	STD 784	.375 NPT Allen Head Plug (Lycoming)
1	1008	Service Instruction (Lycoming)

These Kits are available for \$75.00 from your Mooney Dealer or from:

Mooney Aircraft, Inc.
Spare Parts Annex #1
1712 Water Street
Kerrville, Texas

Shipments can be made immediately upon receipt of firm order.