## Service Bulletin



**NUMBER:** M20-158

**DATE:** 1-22-68

(This Service Bulletin is FAA D.O. Authorization SW-1 Approved)

SUBJECT:

INSTALLATION OF ALTERNATE STATIC AIR

SOURCE PLACARD (DECAL)

MODELS AFFECTED: 1)

M20C, S/N 1852, 1940 thru 670149

M20E, S/N 101 thru 670062 M20F, S/N 660001 thru 670451

2) All aircraft listed above that are equipped with the optional alternate static air source system and which do not have placard (decal)

P/N 950085-47 installed in accordance with the

instructions in this service bulletin.

TIME OF COMPLIANCE:

Mandatory within next 50 hours.

INTRODUCTION:

The alternate static air source instruction placard (decal) was inadvertently omitted from various aircraft having the system. The placard (decal) is required to help the pilot locate and operate

the alternate static source valve.

INSTRUCTIONS:

Adhere placard (decal) to left forward cabin side panel as shown in illustration on reverse side of this sheet. The decal is self adhering (pressuresensitive).

SERVICE BULLETIN KIT:

No. M20-158

950085-47 placard (decal) . . . . . . . . . (one)

Mooney Service Bulletin Compliance

Card . . . . . . . . . . . . . . . (one)


This kit may be ordered free of charge from your nearest Mooney distributor. No direct


factory orders will be accepted.

COMPLIANCE NOTIFICATION:

Upon compliance with this service bulletin, fill out enclosed compliance card and mail

to Mooney Aircraft, Inc.





EMERGENCY MANUAL GEAR OPERATION sticker (only on aircraft equipped with electric gear)